

HEAD MEASUREMENTS

The circumference of the head should be measured at a point approximately one inch above the eyebrows in front and at a point in the back of the head that results in the largest possible measurement. Measure your head several times to make sure you have the largest one.



HELMET SIZE CHART

Hat Size	6 1/2	6 5/8	6 3/4	6 7/8	7	7 1/8	7 1/4	7 3/8	7 1/2	7 5/8	7 3/4
CM	51	53	54	55	56	57	58	59	60	61	62
Helmet Size	XXS	XS	-	S	-	M	-	L	-	XL	XXL